Nº 6546

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-4-56	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 1209	·	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	8' Der
WAS LATERAL AT CURB? Yes		ı
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Under	in & Rina
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.	
	and the second of the second o	42'
		7 deup
W.	More of Particular and any page of the Control of t	45-1 8 de 10
SIGNED Pay Lath	FILED AT ENGINEER'S OFFICE	
/INSPECTOR FOR CIT		

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	stepen jahan jirka milik massigi om Trijaan oo tee maja sa a oo a M	ASSILLON, OHIC	, July	, 30	19
RECEIVED OF_	min Ette	J.,	J	/ . FEE OF 5 3	<u>,</u>
FOR WHICH PERMISSIO	N IS GRANTED MALO	7/200		Cu ti	
	To., SEWER		Sout	7	• •
Commission of the Commission o	end nE AVE. TYPE		Pane		1.
· · · · · //	LOT NO. 1/158		U		
WORK TO BE DONE IN	ACCORDANCE WITH ORDINANC	E No. 2323, DL	JLY PASSED BY T	HE CITY COU	NCIL

NAME OF CONTRACTOR As land & Hengley

Rules of the Department of Public Service.

Nº 6546

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.