

Nº 6547

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

7-30-56

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

270

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

32'

6' DEEP

WAS LATERAL AT CURB?

Yes



WAS ATTACHED TO MAIN

No

NAME OF CONTRACTOR

Valens & Pinsky

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Ray Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.