Nº 6563

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-4-6-6	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. /323	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED 611 U	DISTANCE FROM FIRST MANHOLE P DOWN STREAM TO DITCH AT CURB LINE AND DEPTH DI UND STREAM MAN 900
WAS LATERAL AT CURB? VES	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Willow & Pingley
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
	101
	1 / Cour
	$-N \rightarrow 1/8$
	L'édul
SIGNED Pay La	than filed at engineer's office 7/ 0
' INSPECTOR FOR CI	10°6/-56
REMARKS	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6563

PERMIT TO TAP SEWER

and the second s	MASSILLON, OHIO, 9/5/57, 19.
~ 1	Run Cles FEE OF 52 -
	99 Jot
TO TAP Samulam SEWE	R ON THE
of 3 nd // AVE. TYPE	
THE PREMISES BEING LOT NO. 5396	, HOUSE NO

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL. RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Andrew Dan John Congles

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.