Nº 6569

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 7-8-5 C | IF SO HOW AND LOCATION FROM WYE 76 7 10- |
|------------------------------------|---|
| SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH |
| WAS ATTACHED TO MAIN Yes | NAME OF CONTRACTOR P. Penley |
| SHOW BY DIAGRAM RELATION OF LATE | RAL TO WALL OF BUILDING SERVED. |
| | |
| | |
| \mathcal{D} | 1 Vicuel |
| SIGNED / W LATAO INSPECTOR FOR CIT | FILED AT ENGINEER'S OFFICE |

Nº 6569

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| \mathcal{Q} |
|---|
| Massillon, Ohio, / |
| RECEIVED OF PROMISE FEE OF 5 2 - |
| FOR WHICH PERMISSION IS GRANTED ALE A BULLAR |
| |
| TO TAPSEWER ON THE |
| OF THE ST. TYPE OF STREET |
| THE PREMISES BEING LOT NO. |
| WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE. |
| NAME OF CONTRACTOR |
| Note This permit covers work outside of building only. Any work in |

walls of building is subject to Massillon Board of Health Regulations.