## $N^{o}$ 6586

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED _//- 2-5 C	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 549	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH 44 9 0 - 2 P
WAS LATERAL AT CURB? Yes	
WAS ATTACHED TO MAIN NO	NAME OF CONTRACTOR G Decine
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED
e de la companya de l	16
	neup 1
	N
	30
	90mb 1/20 70
2 11 11	
SIGNED ROLL LATTER	FILED AT ENGINEER'S OFFICE
/ INSPECTOR FOR CIT	Temple a transfer and the second seco
REMARKS	

## Nº 6586

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Massillon, Ohio,
RECEIVED OF 4 A CALL FEE OF 5
FOR WHICH PERMISSION IS GRANTED DENNET
TO TAPSEWER ON THE
OF (T. ) AVE. TYPE OF STREET
THE PREMISES BEING LOT NO. /// 3 , HOUSE NO. 549
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
/Ci
NAME OF CONTRACTOR

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.