## $N^{o}$ $_{6605}$

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	•	
DATE INSPECTED 11-23-56	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 42	FIRST MANNOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	4'000
WAS LATERAL AT CURB?	and the second of the second o	
WAS ATTACHED TO MAIN VES	NAME OF CONTRACTOR	Diane
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	
	en Britan (17 St. 11 St	26'
		1-4 dell
	<u> 58'</u>	Lyaup
SIGNED HINDER FOR CITY	FILED AT ENGINEER'S OFFICE	11-15-57
REMARKS		

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

where  ${f No}$  , 16605 , which is  ${f PE}$ 

Massillon, Ohio, 19:
RECEIVED OF ALL POR PARIS + June Barrater OF 5 2 100
FOR WHICH PERMISSION IS GRANTED
TO TAP SEWER ON THE
OF AND 77 LAVE. TYPE OF STREET MINT
THE PREMISES BEING LOT NO. 3.5/9 HOUSE NO. 42
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL.
RULES OF THE DEPARTMENT OF PUBLIC SERVICE,
NAME OF CONTRACTOR

Note This permit covers work outside of building only. Any work in

walls of building is subject to Massillon Board of Health Regulations.