## Nº 6613

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM TAPPED ONTINAKSE
HOUSE NO	12 upstr
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	
WAS ATTACHED TO MAIN Ves	NAME OF CONTRACTOR NIBON & Pringles
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	7-1
<i>N</i> →	Clearly 13%
SIGNED Poy Latha	FILED AT ENGINEER'S OFFICE // 27-55
REMARKS	

Nº 6613

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

en e	The state of the Massillon, Ohio,	MAU. 10 19
RECEIVED OF LAND	and & Rinkey	( 전투달
4 - 44.5	ED PORKES Rubber	
	SEWER ON THE	south
of Johnshi	• •	lost
	209 310 HOUSE NO	1875
A section of the sect	NCE WITH ORDINANCE No. 2323, DULY P.	ASSED BY THE CITY COUNCIL,
NAME OF CONTRACTOR WAR	•	
	covers work outside of building	g only. Any work in

walls of building is subject to Massillon Board of Health Regulations.