Nº 6619

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		•	-:
HOUSE NO.	_			
SIZE OF PIPE USED	DISTANCE FROM FIRST,MANHOLE. DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	·		
WAS LATERAL AT CURB?	Parent			
WAS ATTACHED TO MAIN	- NAME OF CONTRACTOR	-		
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SE	RVED.		
		e e e e e e e e e e e e e e e e e e e		
				. •
i taman kanala kanala da kanala (
· · · · · · · · · · · · · · · · · · ·				
1000				
SIGNED	FILED AT EN	IGINEER'S OFFICE		
INSPECTOR FOR C	ITY			

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Nº 6619

MASSILLON, OHIO. 100 dy 19.
RECEIVED OF Bentrice Cherry FEE OF \$ 200
FOR WHICH PERMISSION IS GRANTED Allw.
TO TAP SEWER ON, THE MARKET
OF Ankloured D. Y. AVE. TYPE OF STREET Klich
THE PREMISES BEING OF NO. 9777 HOUSE NO. 820
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,
Rules of the Department of Public Service.
(C) Desira
Name of Contractor 1. A war work on the Iding only Any work in
Note This permit covers work outside of building only. Any work in

walls of building is subject to Massillon Board of Health Regulations.