Nº 6640

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	_ IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO 8/7	_	
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	6'De
WAS LATERAL AT CURB? YES		
WAS ATTACHED TO MAIN	- NAME OF CONTRACTOR	-ama
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	Indust.
الحالية في المنظمة المنظمة والمنظمة والمنظمة والمنظمة والمنظمة والمنظمة والمنظمة والمنظمة والمنظمة والمنظمة و المنظمة		
erreta servici e en la comenza e successiva de la comenza de la comenza de la comenza de la comenza de la come	to the control of the first and a few and a second part of the control of the con	16
	and the company of the secondary of the second control of	1
*		42' 60
P. Yes	The state of the s	72 83
SIGNED THE INSPECTOR FOR C	FILED AT ENGINEER'S OFFICE	
REMARKS		

Nº 6640 PERMIT TO TAP SEWER

	the specific terms as	Mace	ILLON, OHIO,	1/2	5
RECEIVED O	F G Q	10 20 20 20 10 10 10 10 10 10 10 10 10 10 10 10 10	Ja / N	9	E OF 5
FOR WHICH PERMIS	SION IS GRANTED	Lang	O Far	nie de	
TO TAP	Lange Land	SEWER ON	THÈ W		
OF (1)	Market Co.	AVE. . ST. TYPE OF S	STREET		Jos Lin
THE PREMISES/BEIN	IG LOT NO. 8576	- n7	, HOUSE NO	. (17	1
WORK TO BE DONE	IN ACCORDANCE WITH	ORDINANCE N	o. 2323, DULY F	ASSED BY THE	CITY COUNCIL
RULES OF THE DEF	PARTMENT OF PUBLIC SER	RVICE.	14		
NAME OF CONTRAC	TOR		*		

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.