Nº 6646

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-14-57	IF SO HOW AND LOCATION FROM TOPPED (4' UP STYPAM)
HOUSE NO. 1185	- UP
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT
WAS LATERAL AT CURB? No	CURB LINE AND DEPTH
WAS ATTACHED TO MAIN YES	- NAME OF CONTRACTOR DROED
SHOW BY DIAGRAM RELATION OF LAT	TERAL TO WALL OF BUILDING SERVED.
	3
	1 2 deep
\checkmark	10 de por 90 miliones de la companya del la companya de la company
**************************************	25
SIGNED Por Fother	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR (ary A republic of the operation of the office of the second
REMARKS	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Massillon, Ohio.
A
RECEIVED OF XXLAMA) / SALAMA FEE OF 5 2
FOR WHICH PERMISSION IS GRANTED (1/1/2) Galler
TO TAP NULL SEWER ON THE
OF BURN ME ST. TYPE OF STREET M.C.
THE PREMISES BEING LOT NO. 1/129 , HOUSE NO. 1/85
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR MICHALLI BAGEL
Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.

3-14-57