Nº \_6653

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM
HOUSE NO.	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
	NAME OF CONTRACTOR  ATERAL TO WALL OF BUILDING SERVED.
7	
SIGNED INSPECTOR FO	FILED AT ENGINEER'S OFFICE
DEMARKS	

Extrag Cumil

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

## N? 6653

	Massillon, Ohio,	March 7 19
RECEIVED OF SUNDAUND.	Maurer	FEE OF \$ CX
FOR WHICH PERMISSION IS GRANTED 40	Wild main	er
TO TAP 1 StOW. 5	EWER ON THE	1111
	YPE OF STREET	List .
	172 , HOUSE NO	682
WORK TO BE DONE IN ACCORDANCE WITH ORDIN		SED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.		

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.