

No. 6658

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3/19/57

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1009

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 97' 7' Deep

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Harry Urban

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED William E. White
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

8-21

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

N^o 6658MASSILLON, OHIO, March 18, 1919RECEIVED OF John GluckFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED John GluckTO TAP DrainSEWER ON THE WestOF 2107 S. W. Ave.

AVE.

ST. TYPE OF STREET WestTHE PREMISES BEING LOT NO. 8975-8976HOUSE NO. 1009

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL.
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Harry B. Urban

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.

4-1-57