

Nº 6662

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3/22/57

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 56 1/2' from M.H. 7' deep

HOUSE NO. 3246

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Harry Urban

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED William C. Whit
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
OFFICIAL NO 6662 PERMIT TO TAP SEWER

MASSILLON, OHIO, March 21 1919

RECEIVED OF Glick Bros. FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Glick Bros.

TO TAP San. SEWER ON THE north

OF Carson N. W. AVE. ST. TYPE OF STREET West

THE PREMISES BEING LOT NO OL 209, HOUSE NO. 3246

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Harry B. Urban

Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.