N_{\cdot}^{0} 6683

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

		-4
DATE INSPECTED 6-25-5	= " " " TO IT KIND LOCKTION PROM	1
HOUSE NO. 3/50	FIRST MANHOLE DOWN STREAM	1
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB7 NO	to the second of	
WAS ATTACHED TO MAIN NO	NAME OF CONTRACTOR HM Way	
SHOW BY DIAGRAM RELATION OF LAT	TERAL TO WALL OF BUILDING SERVED.	
☆		
	17 Jaup	
and the state of t	and the same wife and a commence was a man a same Zoll and the	٥
ار میں العملی از میں العملی	- 0/2h	/
		n digerier Begannen
SIGNED Port Katha	10	
INSPECTOR FOR	FILED AT ENGINEER'S OFFICE	1. 3. 3. 4. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5.
DEMARKS TO SERVE AS	were to the	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

74. 6683	PERMIT TO TAP SEWER	-
Rila	Massillon, Ohio, Mail 14	19
RECEIVED OF	Harrel & Hickary FEE OF 5 25	7 7
OR WHICH PERMISSION	1-41191 - 4/2 40	
OTAP SLACE	1. SEWER ON THE RUCTH	*
- Linealie	AVE. TYPE OF STREET feaved	
		é .

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR HARRY B. Wibau

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.