## $N_{\cdot}^{0}$ 6693

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-6-57	7 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. /2//			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 44		
WAS LATERAL AT CURB? YES			
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED			
and the second s	<i>L'</i>		
· · · · · · · · · · · · · · · · · · ·	N Theep 50.		
	40ee10		
SIGNED PO INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE		
REMARKS			

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6693

## PERMIT TO TAP SEWER

	Massillon, Ohio,	ne 5 19.
RECEIVED OF HERry Hely	an I	FEE OF \$^_
FOR WHICH PERMISSION IS GRANTED BLA	(lane)	
1	WER ON THE AUC	T.
12th 1/ 18 AME	PE OF STREET ALC	
THE PREMISES BEING LOT NO. 2262	, HOUSE NO,	1211
WORK TO BE DONE IN ACCORDANCE WITH ORDIN RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	ANCE No. 2323, DULY PASS	ED BY THE CITY COUNCIL.
NAME OF CONTRACTOR Askanl		
Note This permit covers work	outside of building o	nly. Any work in

walls of building is subject to Massillon Board of Health Regulations.