Nº 6704

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH  7 Deck
WAS LATERAL AT CURB? VES	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR AMAIN
SHOW BY DIAGRAM RELATION OF LATER	
	7 desp
N	— a m m d d m m m m m m m m m 4/1.
	1
	niano
	10' Total
SIGNED Por Katham INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE
REMARKS	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N	Ō	1	6704	
			114117	

## PERMIT TO TAP SEWER

	"* <sub>*.</sub>		/		
			7/	*	
		Massillon, Ohio,			19.
RECEIVED OF	Lange B	link		_ FEE OF \$4	200
FOR WHICH PERMISSION	S GRANTED	no ) Thok	) : 0 1		- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
TO TAP		EWER ON THE	E		
or		YPE OF STREET	ind		
THE PREMISES BEING LO	r NO. 8999	, House No	. /0	18	
WORK TO BE DONE IN A	CCORDANCE WITH ORDIN	ANCE No. 2323, DULY F	ASSED BY	THE CITY (	COUNCIL,
RULES OF THE DEPARTM	ENT OF PUBLIC SERVICE.	•			
Name of Contractor_	lechans				
76. /TOL *	•.				, .

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.