## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-23-57	FIRST MANHOLE DOWN STREAM 10 up them M 90
HOUSE NO. 570	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR ODione
SHOW BY DIAGRAM RELATION OF LATE	
	\1\1\2\2\1\1\1\1\1\1\1\1\1\1\1\1\1\1\1\
igasata kanta japan kanjakusuki risu ta <b>M</b> uk <del>e uta.</del> Tarifan	The state of the second state of the second
SIGNED Por Lathern	FILED AT ENGINEER'S OFFICE
REMARKS	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6711	PERMIT TO	O TAP SEWER
en e	e ea la company de la comp La company de la company d	ню. 7/3/57
RECEIVED OF	Ma A Bear.	FEE OF \$ 2
FOR WHICH PERMISSION	IS GRANTED Dume:	
ТО ТАР	SEWER ON THE	E
OF 1 1 10 10	AVE. TYPE OF STREET	dist
· 1	OT NO. /// 57/ HC	
	ACCORDANCE WITH ORDINANCE No. 2323, MENT OF PUBLIC SERVICE.	DULY PASSED BY THE CITY COUNCIL,
•	<b>(</b> )	

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.

NAME OF CONTRACTOR\_