Nº 6712

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-25-57 IF SO FIRST	HOW AND LOCATION FROM WYE 144' 9'De
HOUSE NO	
SIZE OF PIPE USED // DOWN	NCE FROM FIRST MANHOLE STREAM TO DITCH AT LINE AND DEPTH
WAS LATERAL AT CURB? NO	
WAS ATTACHED TO MAIN YES NAM	
SHOW BY DIAGRAM RELATION OF LATERAL TO	
	<u> </u>
alama ij	in my many many many many many many many
$\mathcal{N} \longleftarrow$	
	2/2×1/5-8
	A 144 \\8'1
s. Augustus	0 174 V 8 1
SIGNED Por Vatham	FILED AT ENGINEER'S OFFICE 11-16-57
·	
REMARKS	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

where $oldsymbol{N}$	ro 6712	r and Video	MARCH P	ERMIT	TO	TAP	SEWE	R
				Massillo	N, OHIO,	. 7.,	3/57	19.
	RECEIVED OF	- 11-	4. A.	Bed	مبر	,	FEE O	of \$ 2 (0.4)
FOR V	WHICH PERMISSI	- ON IS GRANTED	A Dec	imes				
TO TA		Lan	/	SEWER ON THE		6		-
OF	10000	The Mark Style		TYPE OF STRE		di	AL	
THE I	PREMISES BEING	LOT NO			_, HOUSI	E NO	5/6	
• .	K TO BE DONE I	·	E WITH ORDI	NANCE NO. 2	323, DUI	Y PASSE	D BY THE CI	TY COUNCIL,
Rule	S OF THE DEPAR	RTMENT OF PU	BLIC SERVICE.					
· Name	E OF CONTRACTO	DR	Lean	<u>.</u>)	***************************************			
nom a reconstruction of the section	Note Thi	s permit co	overs worl	c outside o	of build	ding on	ly. Any	work in

walls of building is subject to Massillon Board of Health Regulations.