## Nº 6731

# FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-21-57	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	Tapped	RO'	110
HOUSE NO. 2869				
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	n den sy tat de		4
WAS LATERAL AT CURB? NO	the second secon	in an industry and participations of the second sec		
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR	90	<u>ceno</u>	
SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SE	RVED.		
			1	
	ing the state of t	Joen Toler		
		o et sera, da dil	134	100
		•	X w	up Tap
	/	2 // 2		801
Part 4 -	•	GINEER'S OFFICE	m. 61	
SIGNED INSPECTOR FOR CITY	FILED AT EN	GINEER'S OFFICE	1/ REWY	<u> </u>
REMARKS			• •	

#### OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## No 6731

### PERMIT TO TAP SEWER

MASSILLON, OHIO,	<u>5</u> 19
RECEIVED OF	FEE OF \$ 2
FOR WHICH PERMISSION IS GRANTED	
TO TAPSEWER ON THE	
OF Palas MW AVE. TYPE OF STREET A: L	
THE PREMISES BEING LOT NO. 4 182 HOUSE NO. 28	34
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	THE CITY COUNCIL
NAME OF CONTRACTOR Le anal	
Note This permit covers work outside of building only.	Any work in

walls of building is subject to Massillon Board of Health Regulations.