

No. 6736

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8/15/57

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

12' 10' deep

HOUSE NO. 2507

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR REMELY - DIXON

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED W. E. [Signature]
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

The sewer was into the prob. line but was not
deep enough so it was taken out & re-layed.

8-3
CITY OF MASSILLON, OHIO

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

CERTIFICATE NO. 6736

PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/14 1914

RECEIVED OF Joe Valpey

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED C. R. Pfenkler

TO TAP San

SEWER ON THE D

OF Shank NE

AVE.

ST. TYPE OF STREET Black Dug

THE PREMISES BEING LOT NO. PL 40 314

HOUSE NO. 2507

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 3323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE

NAME OF CONTRACTOR Remley (Valpey)

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.