FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-3-57	IF SO HOW AND LOCATION FROM LIVI 290 (Dee
HOUSE NO. 526	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB7	
WAS ATTACHED TO MAIN 195	NAME OF CONTRACTOR 9 Decense
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
and the second second second second	
	20'
$N = \frac{1}{2}$	201 Pelaps
	0 290' 1 Vida
SIGNED Properties SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE 11-15-57
REMARKS	*

Nº 6741

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF 1. 4 S. Quilders Suc FEE OF 5 2 CM
FOR WHICH PERMISSION IS GRANTED
TO TAP DAW SEWER ON THE LAST
OF CARULE MILL ST. TYPE OF STREET AUX
THE PREMISES BEING LOT NO. 1/6 36 , HOUSE NO. 526
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR A duana
Note This permit covers work outside of building only. Any work in

walls of building is subject to Massillon Board of Health Regulations.