$N_{\rm c}^{\rm o}=6753$

DATE INSPECTED 9-4-57 IF SO HOW AND LOCATION FROM V 1/ 17/1	9'Deel
HOUSE NO. 7138	
SIZE OF PIPE USED CONSTREAM TO DITCH AT CURB LINE AND DEPTH	· · · · · · · · · · · · · · · · · · ·
WAS LATERAL AT CURB? NO	
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR GOL	- Lung
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	ľ
	14'
	1 n'oxel
e de se maior de deserva de la composição d Productiva de la composição de	50
	10') Vs'
SIGNED Port allem FILED AT ENGINEER'S OFFICE	, dans
Vinspector for city	15-15/
REMARKS	

Nº 6753

PERMIT TO TAP SEWER

MASSILLON, OHIO, 15 19
RECEIVED OF 11 4 () Duildus Jul FEE OF \$ 200
FOR WHICH PERMISSION IS GRANTED
TO TAP DUW SEWER ON THE MATCH
OF Allen, MU AVE. TYPE OF STREET derd
THE PREMISES BEING LOT NO. 1164/, HOUSE NO. 2138
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR A & XUAUX
Note. This permit powers work outside of building only. Any work in

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.