No. 6770 AND SIGNED WHEN RETURNED

DATE INSPECTED 10-3-57	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO	-	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 78	7'DEEP
WAS LATERAL AT CURBY YES	and the second s	•
WAS ATTACHED TO MAIN	- NAME OF CONTRACTOR	Whan .
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	
 Substitution of the second of t		121
N and I		7'cleep
er in this end by RK (RE bounds, India)	e in the second of the windowski to the second of the seco	198'
		> 16'
		7dup
Pr. G.A.		1
SIGNED / INSPECTOR FOR C	Z FILED AT ENGINEER'S OFFICE	
化二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十	しょうほう 大学はこれ 一切 はないとうにっけん めき あじんし おきまだける 野乳 動作を通過する こうしょう	

REMARKS

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, ALL 195
RECEIVED OF Narry B Urban FEE OF 5 2-
FOR WHICH PERMISSION IS GRANTED BYROW Heltz
TO TAP PAUL. SEWER ON THE EAST
OF Miles D. W. AVE. TYPE OF STREET hard
THE PREMISES BEING LOT NO. 8958 , HOUSE NO. 1016
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.