## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED AND SIGNED WHEN RETURNED

DATE INSPECTED 10-15-57	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 636		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE.  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	5 /2 0201
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	inle
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	N Vo. 4
		1 56
W — I		10 5-12 Dec10
SIGNED Port Latha	FILED AT ENGINEER'S OFFICE	27'
INSPECTOR FOR CIT		
REMARKS		

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

## Nº 6773

		Massillon	ı, Оніо <u>, /</u> о/	19.
RECEIVED OF.	A. No.	may !	e	FEE OF \$
FOR WHICH PERMISSION	ON IS GRANTED	Casto K	1 Adom)	
TO TAP	1	SEWER ON THE	E	
OF	1988 1997	AVE. ST. TYPE OF STREE	T 4 0	2111/
THE PREMISES BEING	257/6 LOT NO. 7/1/2		, HOUSE NO,	<u> </u>

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Dect

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.