

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
No. 6775 AND SIGNED WHEN RETURNED**

DATE INSPECTED 12-23-57

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1819

SIZE OF PIPE USED 16"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR P. Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



1 1/2' deep

54'

3' 9" deep

SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

16-17 1-15-20
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 6775

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/11/1919

RECEIVED OF

R. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

None

TO TAP

Man

SEWER ON THE

P.

OF

Massachusetts

AVE.

ST. TYPE OF STREET

dent

THE PREMISES BEING LOT NO.

6365

HOUSE NO.

1819

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.