

Nº 6780

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-29-57

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 931

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

291' 2' DEEP


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

P. Marks

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy K. Nathan

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

Rock at curb

7-17

7-17

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 6780

PERMIT TO TAP SEWER

MASSILLON, OHIO.

Oct 21 19.

RECEIVED OF

Roscoe Marks

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Buron E. Hables

TO TAP

Sewer

SEWER ON THE

South

OF

North S.W.

AVE.

ST. TYPE OF STREET

Hard

THE PREMISES BEING LOT NO.

11302

HOUSE NO.

931

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL.
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Roscoe Marks

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.