

Nº 6782

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED**

*storm  
sewer*

DATE INSPECTED \_\_\_\_\_

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_

HOUSE NO. \_\_\_\_\_

SIZE OF PIPE USED \_\_\_\_\_

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_

WAS LATERAL AT CURB? \_\_\_\_\_

WAS ATTACHED TO MAIN \_\_\_\_\_

NAME OF CONTRACTOR \_\_\_\_\_

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED \_\_\_\_\_

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE \_\_\_\_\_

REMARKS \_\_\_\_\_

2-19 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

NO. 6782

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/31 19

RECEIVED OF

R. G. Marko

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

Storm

SEWER ON THE

OF

3rd NW

AVE.

ST. TYPE OF STREET

Hard surface

THE PREMISES BEING LOT NO.

P. 16 11

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R. G. Marko

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.