Nº 6792 AND SIGNED WHEN RETURNED

DATE INSPECTED 11-26-57	I IF SO HOW AND LOCATION FROM INM 8/2.0 et
HOUSE NO. 24+6	<u> </u>
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	no de la companya de
WAS ATTACHED TO MAIN YES	- NAME OF CONTRACTOR - A Dieine
SHOW BY DIAGRAM RELATION OF LAT	TERAL TO WALL OF BUILDING SERVED.
and the second s	Morolo Line
V	and the second of the second s
/V	
R-14-	2131
SIGNED INSPECTOR FOR C	FILED AT ENGINEER'S OFFICE
REMARKS	

9-45-

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6792

PERMIT TO TAP SEWER

	MASSILLON, OHIO, 19
	RECEIVED OF FEE OF \$ 2 -
	FOR WHICH PERMISSION IS GRANTED TO THE STATE OF THE STATE
•	TO TAP
	OF AVE. TYPE OF STREET.
	THE PREMISES BEING LOT NO. 1314 HOUSE NO. 1475
¥.	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
	RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.