Nº 6796

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM TRANSCE (1' 5.00 Heal
HOUSE NO. /2 3	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURE? NO	The state of the s
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
	7 du
M —	vogan den en er de de konsjona en man ja sje anver
	0 61' 9'1
SIGNED Port Nathan	FILED AT ENGINEER'S OFFICE
/ INSPECTOR FOR CI	Y. with the street there is painting the other and the last the street

Nº 6796 OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Subset of set seems	
FOR WHICH PERMISSION IS GRA	NTED	
$\mathcal{A}_{\mathcal{A}}$	/ · · · · · · · · · · · · · · · · · · ·	
		dist
· A	Citala	그리가 그 이 눈이 이 것 같고 그 일이 이렇게 되었
		3, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF NAME OF CONTRACTOR	F PUBLIC SERVICE,	
		building only. Any work in

walls of building is subject to Massillon Board of Health Regulations.