## Nº 6801

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED /2-/7-57	FIRST MANHOLE DOWN STREAM IN MH OH OHIO
HOUSE NO. 839	
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR PAymey
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
	& AB'
	32 Tochero
SIGNED Roy Lathon INSPECTOR FOR CITY	FILED AT ENGINEER'S DEFICE
REMARKS Reclary	na tiutuit et majaur ei jauliikuni (ameri
$\sim$	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## PERMIT TO TAP SEWER

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Ram De y

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.