N° 6808

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED /- 12-5-8	IF SO HOW AND LOCATION FROM TOPPED M. IST MOTEL
HOUSE NO. 50 /	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR R. Rember
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.
where the contradiction of the second contradiction of th	o'
and the configuration of	State of the state
inger state of the control of the co	N = 1 deep
	the second of th
	Tapped My
SIGNED Poy Yatham	FILED AT ENGINEER'S OFFICE
/ INSPECTOR FOR C	
DEMARKS	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

$N\mathbf{\hat{o}}$	6808 Room	PERMI	T TO TAP SEWER
Hecc	rasin.	Massil	LON, OHIO, // ~7.31
	PERMISSION IS GRANTED.	12) 20 10	FEE OF \$ 1
то тар	1.420	sewer on T	
OF		AVE. TYPE OF ST.	
WORK TO BE	,	WITH ORDINANCE No.	. 2323, DULY PASSED BY THE CITY COUNCI

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.