Nº 6812

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-8-5-8	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH AS-/ X DE-CP
WAS LATERAL AT CURB? Ve.S	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	V
diga waxa ana walay laya waxa waxa ka baba bira	The state of the s
A Company of the Comp	
	SAND
SIGNED Por Lathan	FILED AT ENGINEER'S OFFICE
/ INSPECTOR FOR CIT	
DEMARKS	电影 化二氯基甲 的复数经营制度 医静脉 化二氯甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基

Nº 6812

PERMIT TO TAP SEWER

	MASSILLON, OHIO, Joh 6 19
RECEIVED OF	ma FEE OF \$ 25
FOR WHICH PERMISSION IS GRANTED HAAD	old Thomason
TO TAP SEV	NER ON THE MORTH
OF AMALY ME AVE.	PE OF STREET dirit
THE PREMISES BEING LOT NO. 11371	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.