

Nº 6818

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-19-58

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

Tapped MH 8' Dec

HOUSE NO. 1601

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH



WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

R. R. Penley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

14-4

5-31-3

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 6818

PERMIT TO TAP SEWER

MASSILLON, OHIO,

3/25

19

RECEIVED OF

Raymond Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Paul King

TO TAP

San

SEWER ON THE

W

OF

East Main

AVE.

ST. TYPE OF STREET

Paved

THE PREMISES BEING LOT NO.

9977

HOUSE NO.

1601

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.