Nº 6828 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-16-5-8	FIRST MANGED DOWN STREAM 208 From EAST CURBO
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? No	en de la companya de La companya de la co
WAS ATTACHED TO MAIN Ye.s	NAME OF CONTRACTOR & Nogt.
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.
	10'pee10
SIGNED ROY THOMAS INSPECTOR FOR CI	FILED AT ENGINEER'S OFFICE PECLOSOR
3 5 to 1767 3 1 5 4 3 m²	

-14

Nº 6828

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, Clfred 14 19
RECEIVED OF What Const Co FEE OF 5 2 00
FOR WHICH PERMISSION IS GRANTED MANUELLAW SALVEY TO LOW CO
TO TAP DAW SEWER ON THE HUN FARMEN FIRST & Felle
OF Federal avr/1/5 AVE. TYPE OF STREET frued
THE PREMISES BEING LOT NO. 70-71 , HOUSE NO. 54
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
BILLER OF THE DEPARTMENT OF PURIL SERVICE

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.