## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED AND SIGNED WHEN RETURNED

DATE INSPECTED 4-23-58	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 7/2	TEVAY CT	
SIZE OF PIPE USED 9"	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH  ON THE PROPERTY OF	
WAS LATERAL AT CURB? YES	orange en al angele en	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR D. Boge	
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.	
en a manual agree de la companya de	4"Pipe	く
	and	(
ent and carbon a larger site of the	30	
	1812 K7 cheep	ŧ
- Marie Control	WALES CO.	Þ
SIGNED	FILED AT ENGINEER'S OFFICE	-
INSPECTOR FOR CITY	Y control of the cont	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE Nº 6832 PERMIT TO TAP SEWER

and the second s	MASSILLON,	Оню,	1//23	/58 11
RECEIVED OF Jurain Son	w		·	FEE OF \$
	elast	Ric		
TO TAP SEV			<u> </u>	
OF MANE. TY	PE OF STREET		-=	
THE PREMISES BEING LOT NO. 1182- 83- 8	<i>f</i> .	HOUSE NO.	71	2
- WORK TO BE DONE IN ACCORDANCE WITH ORDINA	NCE NO. 232	23, DULY PA	SED BY,TI	HE CITY COUNCI

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.