

N^o 6838

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-19-58

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1825

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

78' 7' Deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR

Beaver Const.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

6-48
48

2-11-58

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 6838

PERMIT TO TAP SEWER

MASSILLON, OHIO, May 19, 1958

RECEIVED OF

Banner Paint

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Harold Krantz

TO TAP

main

SEWER ON THE

west

OF

11th NE

AVE.

ST. TYPE OF STREET

paved

THE PREMISES BEING LOT NO.

8430-8431

HOUSE NO.

1825

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Banner Paint

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.