Nº 6844

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-2-1-58	IF SO HOW AND LOCATION FROM TAPPED 323 EASTOFME
HOUSE NO. 229	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? /YO	and the second of the second o
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR W. Millan P. Remley
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	16 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	7 deep 66 city paid for . Lateral that is in main to c
	323'
SIGNED Roy Latha	FILED AT ENGINEER'S OFFICE
REMARKS Rember Grand	Pun l

3-33

Nº 6844

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, May 22 19.
RECEIVED OF HARRY (3 Unland) FEE OF \$ 200
FOR WHICH PERMISSION IS GRANTED ALANCE THE THIRD AND A LOW
FOR WHICH PERMISSION IS GRANTED // WALLET / TO COMMISSION IS GRANTED
TO TAP AQUI. SEWER ON THE SOLITA
OF JABO 97 6. AVE. TYPE OF STREET Acled
THE PREMISES BEING LOT NO. PT 961 , HOUSE NO. 229
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR HARALI B. THILMIN
\mathcal{A}

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.