Nº 6847

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED _ 5-31-58	IF SO HOW AND LOCATION FROM 11 4// 3/2	, 8 Dee
HOUSE NO. 1328		No.
SIZE OF PIPE USED	DISTANCE-FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? NO	o <u>lima Tu</u> rana na n <mark>aminina nam</mark> ana 2008 ta 1945 na na 1958 na	
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR	appo
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.	-
	457	12
		1 / Tolup
A compared to the second of th	The recognition of the property of the property of the second of the sec	/42'
	<u> 34'</u>	Krocep AUL
SIGNED TOTAL	FILED AT ENGINEER'S OFFICE	7.02.2/5
REMARKS	Marithanillan relikus i prolikting terr	

Nº 6847 OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	nga minanga sa sa Mananga mananga sa	arin kanan alah bili bili bili bili bili bili bili bil	Massil	LON, OHIO,	Brey	28 19
REC	EIVED OF	A G	Die	y ke		FEE OF \$
	The second	ANTED 1	and everyone in the second			
		ANTED				
)F	Techicos in	77.///. AVE	TYPE OF ST	e ten ente va.	Li.	prive analysis (19)
1.0		11 1/2				
		RDANCE WITH OR				
RULES OF 1	THE DEPARTMENT	OF PUBLIC SERVIC	E.			

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.