$N_{-2}^{0} 6858$

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-16-58 HOUSE NO. 220	IF SO HOW AND LOCATION FROM TOPPED 11' MAIN' 9'0
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? No	and the second second of the first of the second of the sec of the second of the sec
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR - Q Deagnes
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
V	
	5' / 7'cles
	The second of th
	40-17-
SIGNED Poy Pothar	FILED AT ENGINEER'S OFFICE
REMARKS	Partificação per ou liberalista de la filo estrat.

6858 **Nº** : 6858

3171-1-54

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO, 19 19
	MASSILLON, OHIO, 42/16/19
	RECEIVED OF A MINIA PEE OF \$ 2 -
٠.,	FOR WHICH PERMISSION IS GRANTED ALLOW CLASS ALLOW A
,	TO TAP SEWER ON THE MASTE
	OF (1916) A F AVE. TYPE OF STREET ALL
	THE PREMISES BEING LOT NO 17 1075-1074, HOUSE NO. 220
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
	RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
	a O Maria

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.