FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

y f	(amount)	•
DATE INSPECTED	Fro How and Location from	
DATE MOI ECTED	FIRST MANHOLE DOWN STREAM	
To the state of th	THE THRUTTE BOWN BIREAM	
- HOUSE NO	,	
11.000	DISTANCE FROM FIRST MANHOLE	
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT	8 10220
	CURB LINE AND DEPTH	<u> </u>
WAS LATERAL AT CURB?	<u>5 -</u> January Johnson States and	•
WAS ATTACHED TO MAIN	7.9	
	NAME OF CONTRACTOR	- A sure have the world and the test
SHOW BY DIAGRAM RELATION OF	LATERAL TO WALL OF BUILDING SERVED.	
-	en de la composition de la composition La composition de la	demand and deliver on the letters are thought to mercentally
		/ In dell'
	والمرابع المناز المرابع المحارف والأراث والمستريق فلأوساء وسنتأك ويروا أبار والمرابع والمحار	- a /
and the second s		A A
		<i>y</i> 1
and the first of the same of the second and the same of the same o		C. C.
· · · · · · · · · · · · · · · · · · ·	and the contract of the second	
		12
	And the second section of the section of the second section of the section of the second section of the section of th	market of the state of the stat
	The second secon	
	A CONTRACTOR OF THE CONTRACTOR	
Company of the second		
SIGNED 10721 8 00 30	FILED AT ENGINEER'S OFFICE	•
/ INSPECTOR F	OR CITY	
for the state of t		
REMARKS		

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6865

PERMIT TO TAP SEWER

	τ
	MASSILLON, OHIO,
	RECEIVED OF THE OF \$ 2 -
76	FOR WHICH PERMISSION IS GRANTED () () () () () () () () () (
	TO TAP
	of / / / P) Cave. Type of STREET
	THE PREMISES BEING LOT NO. 90 363 HOUSE NO. 2015
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.