### Nº 6867

# FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3 - 28-3	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 1923		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	7/10-04
WAS LATERAL AT CURB?	and the second s	•••
WAS ATTACHED TO MAIN	— NAME OF CONTRACTOR	Samuel Sa
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERVED.	
	and the first of t	(M
	ProPLINE	1 8 p- 4
SIGNED Roy att	FILED AT ENGINEER'S OFFICE	C
INSPECTOR FOR	city so nelelekti i et kerkiles et jake listile silbire	

-11-5

#### OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº0 6867

## PERMIT TO TAP SEWER

	te viego in November i navide in Policina i November i	Massillon, Ohi	10,	<u> </u>	<b>∋</b> !
RECEIVED OF	1, 0, 10:	(m)		_ FEE OF \$	·c
	17,10	B	in a super		
TO TAP	S GRANTED SEW		12)		_
OF COLLAND	AVE.	E OF STREET	H.L		
THE PREMISES BEING LO	111171			123	-: -: -:
*	CCORDANCE WITH ORDINAL ENT OF PUBLIC SERVICE.	ICE NO. 2323, D	ULY PASSED BY	THE CITY COUNC	L,
				the state of the s	

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.