

Nº 6873

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-16-58 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____


HOUSE NO. 700

SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 145' 7' deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR H. Urban

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Latham INSPECTOR FOR CITY
FILED AT ENGINEER'S OFFICE

REMARKS _____

B-15-38

196-471

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 6873

PERMIT TO TAP SEWER

MASSILLON, OHIO, July 15 1924

RECEIVED OF Glick Bros. FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Glick Bros

TO TAP saw SEWER ON THE main

OF Taggart AVE. ST. TYPE OF STREET side

THE PREMISES BEING LOT NO. 11312 HOUSE NO. 700

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Harry A. Watson

Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.