Nº 6875

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED S-/5-58	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		•
HOUSE NO. 820			
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	121'	7'0e+P
WAS LATERAL AT CURB? Yes			
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	N. M	ban
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVE	ED.	
N		ne us shi dana sana	5 5 5
ente en la deservación de la mente en la electrica de la compania de la compania de la compania de la compania	m. m	and the state of t	051
		à	, 31
Roy Y +	5EWC		
SIGNED / WAY / INSPECTOR FOR CIT	FILED AT ENGIN	IEER'S OFFICE	
REMARKS			1

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	211		· '		
RECEIVED OF	. Africa	red Itah.	2 -1 1	The second of th	OF \$
FOR WHICH PERMISS	# 5 \$ 1 2 1 4 1 5 1 2	yKraÿjasad			
FOR WHICH PERMISS	ION IS GRANTED	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	<u>C. K. Start</u>	
TO TAP	ili. Karanan menangan	SEWER C	N THE		
				M.C.	
7 / / / / / / / / / / / / / / / / / / /	7			A Comment	/
	111	//		SE NO	₹ . .
THE PREMISES BEIN	3 LOT NO	-//-2	, Hous	SE NO.	
•	•				
WORK TO BE DONE	IN ACCORDANCE W	TH ORDINANCE	No. 2323, DU	ILY PASSED BY THE	CITY COUNCIL
RULES OF THE DEP		Cenvice		•	

AME OF CONTRACTOR

Nº 6875

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.