FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 6876 AND SIGNED WHEN RETURNED

DATE INSPECTED 8-6-58	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	:
HOUSE NO. 332		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	4 D.
WAS LATERAL AT CURBY Ves		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR // Moran	• .
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.	•
	20	
	1. 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	~1
SIGNED ROY Rath	OAK ST	***************************************
INSPECTOR FOR CITY	rediktanisi en het ine dyanisi et bestiken	- 2
REMARKS		

8-15-5

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Nº 6876

		MASSILLO		1 100	19.
RECEIVED OF	Harry	Weben		FEE OF	5 7
OR WHICH PERMISS	ION IS GRANTED	Dest -	tels ki		vinara (
O TAP	1	SEWER ON THE	.7	et	
ı <u>r 26</u>	17 / E. AVE. ST.	TYPE OF STRE	ET		3
HE PREMISES BEING	LOT NO. 1-667		, HOUSE NO		
OPK TO BE DONE	IN ACCORDANCE WITH ORD	UNIVEE NO 2	TOR VILIO FOR	EED BY THE CITY	COUNCII

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR RANGE Usban

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.