Nº 6878

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| . ~. | DATE INSPECTED 8-9-5-8 | IF SO HOW AND LOCATION FROM 11 73 9 0 - C |
|------|--------------------------------------|--|
| | HOUSE NO. 1322 | |
| | SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH |
| - 2 | WAS LATERAL AT CURB? | |
| | WAS ATTACHED TO MAIN Yes | NAME OF CONTRACTOR Property |
| | SHOW BY DIAGRAM RELATION OF LATER | RAL TO WALL OF BUILDING SERVED. |
| | | 13/ |
| ٠,, | | man and a second of the second |
| | SIGNED ROY Lather INSPECTOR FOR CITY | FILED AT ENGINEER'S OFFICE |
| | REMARKS | |

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6878

PERMIT TO TAP SEWER

| | Massillon, | оню, 8/9 | |
|---------------------------------|---------------------|-----------|----------|
| RECEIVED OF | a marko | | FEE OF 5 |
| FOR WHICH PERMISSION IS GRANTED | (22.0) | N. Ty | |
| TO TAP | SEWER ON THE | 777/ | |
| or Call | AVE. TYPE OF STREET | Aux to | |
| THE PREMISES BEING LOT NO. // | 1827 | HOUSE NO. | |

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.