Nº _6881

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-19-5-8	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 16 10 10 10 10 10 10
HOUSE NO.	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR & Beaute Since.
SHOW BY DIAGRAM RELATION OF LATE	
	70
	HAIN IRd
SIGNED Roy Wathown INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE

Nº 6881 PERMIT TO TAP SEWER

	RECEIVED OF	- Benn	· ///	ILLON, OHIO,	Aug 13	19.
FC	OR WHICH PERMISS	· · · · · · · · · · · · · · · · · · ·	Front M	Eliteail (Church	
тс	TAP	• •	SEWER ON	-		
OF	. TUN	Casi Pil	AVE. ST. TYPE OF S	TREET 1/2	nied	
TH	E PREMISES BEING	5 LOT NO. 04	345	, HOUSE NO	1024	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL.

Rules of the Department of Public Service.

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.