Nº 6882

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-14-5		
HOUSE NO. 611	FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	8 Neep
WAS LATERAL AT CURB? /45		
WAS ATTACHED TO MAIN	- NAME OF CONTRACTOR	enles
SHOW BY DIAGRAM RELATION OF LAT	TERAL TO WALL OF BUILDING SERVED.	
	10'	
	70	
Ŋ	70	10.61
SIGNED KOY Kithan	FILED AT ENGINEER'S OFFICE	<u> </u>
INSPECTOR FOR C	The appraisable of an inner of job in a linguisty	
REMARKS		

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER Nº 6882 MASSILLON, OHIO RECEIVED OF THE PREMISES BEING LOT NO. 15 19 1

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note This permit covers work outside of building only. An

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.