## $N_{\odot}$ 6890

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-1-58	FIRST MANHOLE DOWN STREAM TRPPED 192
HOUSE NO. 390	
SIZE OF PIPE USED	DISTANCE FROM FIRST-MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB?	and the control of th
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR VOE 9 VOE
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
<i>→ ∧</i>	94 - 540
SIGNED William & White	950 FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CI	DY CEMENTY STONE PUT AROUND 17.
REMARKS // VV // V	JI WE POSER & WINE I'VI THOUND II.

17-7

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

1071-53

MASSILLON, OHIO, 15 19	
RECEIVED OF 190 4 Jac FEE OF S 500	
FOR WHICH PERMISSION IS GRANTED M. 4 Duilders	
TO TAP AAW. SEWER ON THE	
OF CARCULAT M. W. ST. TYPE OF STREET	
THE PREMISES BEING LOT NO. 7 Mail laures & 1, House No. 570	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL.	
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR DE V Jae	

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.