Nº 6893

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-30.08	IF SO HOW AND LOCATION FROM Y-36
HOUSE NO. 6/6	_
	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	en de la companya de -
WAS ATTACHED TO MAIN	- NAME OF CONTRACTOR VOET VOE
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.
1 · · · · · · · · · · · · · · · · · · ·	
was the same of th	
V	
84	
4	The second of th
36	→ 18· ←
SIGNED William & Falis	FILED AT ENGINEER'S OFFICE
/ INSPECTOR FOR C	***

17-4

Nº 6893

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

ノクフノアうだ

THE PREMISES BEING LOT NO. 11 Mars Sauce Thouse No. WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL. RULES OF THE DEPARTMENT OF PUBLIC SERVICE. NAME OF CONTRACTOR

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.