Nº 6894

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-20-58 IF SO HOW AND LOCATION FROM 239 40.
HOUSE NO
SIZE OF PIPE USED DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR JOE Y Jac
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
2 20
- 1 20'
20 40 239'
SIGNED REAL STATE FILED AT ENGINEER'S OFFICE 1-18-58
REMARKS

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

## Nº 6894

MASSILLON, OHIO, 654 /5 19
RECEIVED OF BE 4 ME FEE OF \$ 200
The state of the s
FOR WHICH PERMISSION IS GRANTED W. VILLE MILACO
TO TAP DAU. SEWER ON THE
OF MARIS, M. W. ST. TYPE OF STREET
THE PREMISES BEING LOT NO. 11 May Hay 4 House No. 576/
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.